



# Vehicle History Report™

US \$44.99

## 1999 CHEVROLET SILVERADO 1500 LS

VIN: 2GCEC19T9X1161719  
3 DOOR EXTENDED CAB PICKUP  
5.3L V8 F OHV  
GASOLINE  
REAR WHEEL DRIVE

No accidents or damage reported to CARFAX

5 Service history records

At least 1 open recall

CARFAX 1-Owner vehicle

Personal vehicle

199,282 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/8/25 at 12:35:21 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



## Ownership History

The number of owners is estimated

Owner 1

Year purchased

1999

Type of owner

Personal

Estimated length of ownership

26 yrs. 8 mo.

Owned in the following states/provinces

New Mexico

Estimated miles driven per year

8,370/yr

Last reported odometer reading

199,282



## Title History

Owner 1

### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

No Problem

### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

No Problem



## Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

<b>Total Loss</b> No total loss reported to CARFAX.	✓ No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	✓ No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	✓ No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	✓ No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	✓ No Issues Reported
<b>Manufacturer Recall</b> At least 1 manufacturer recall requires service. Check for open recalls or schedule dealer service on GM vehicles at recalls.gm.com.	Recall Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired



## Detailed History



### Owner 1

Purchased: 1999



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
8,370 mi/yr

Date	Mileage	Source	Comments
01/13/1999	103	New Mexico Motor Vehicle Dept.	<b>Vehicle purchase reported</b>
02/20/2000		New Mexico Motor Vehicle Dept. Las Cruces, NM	<b>First owner reported</b> - Titled or registered as personal vehicle
09/13/2000		General Motors	<b>Manufacturer Non-Compliance recall issued</b> - NHTSA #00V097 - Recall #N000045 FRONT SAFETY BELT COMPLIANCE - Status: Remedy Available  Locate an authorized General Motors dealer to obtain more information about this recall.  ⊖ <b>Learn more about this recall</b>

**Description:** Light duty pickup trucks. The seat belts fail to conform to the requirements of FMVSS No. 209, "Seat Belt Assemblies."

The seat belts may not restrain an occupant properly in the event of a crash.

**Remedy:** Dealers will replace both the front driver and passenger seat belts with new seat belts free of charge.

01/09/2001

General Motors

**Manufacturer Safety recall issued**

- NHTSA #00V345
- Recall #N000093 FRONT BRAKE PIPE CONTACT WITH BODY CROSS SILL
- Status: Remedy Available

Locate an authorized General Motors dealer to obtain more information about this recall.

[⊖ Learn more about this recall](#)

**Description:** Light duty pickup trucks and sport utility vehicles. Some of these vehicles have a clearance condition between the front right-hand brake pipe and the body cross sill that could decrease to the point of allowing contact during the life of the vehicle. If contact occurs and the brake pipe becomes damaged, in half of the brake system there can be a loss of brake fluid and pressure. The brake warning lamp will be activated when the brake fluid level reaches the indicator limit.

During braking, the pedal will be lower than normal and stopping distances will be longer. If this occurs when stopping distance is limited, a crash could occur.

**Remedy:** Dealers will inspect the front right-hand brake pipe for wear. If there are signs of wear, this section of the brake pipe will be replaced with a new designed brake pipe section. If there are not signs of wear on the brake pipe, the dealer will install a spacer clip to ensure sufficient clearance between the brake pipe and the body cross sill free of charge.

02/06/2001

New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM

**Registration issued or renewed**

02/12/2002

New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM

**Registration issued or renewed**

02/18/2004

New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM

**Registration issued or renewed**

02/14/2005

New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM

**Registration issued or renewed**

02/13/2006

New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM  
Title #060444S06702861

**Title issued or updated**

- Loan or lien released

04/03/2006

General Motors

**Manufacturer Safety recall issued**

- NHTSA #06V066
- Recall #N060019 TAILGATE SUPPORT CABLE REPLACEMENT
- Status: Remedy Available

Locate an authorized General Motors dealer to obtain more information about this recall.

[⊖ Learn more about this recall](#)

**Description:** Certain pickup trucks have galvanized-braided-steel tailgate support cables used to support the tailgate in the full open (horizontal) position. Over time these cables can corrode and fracture when loads are applied to them.

If one cable fractures, the remaining cable may retain the tailgate in a horizontal position. If both cables fracture, the tailgate would drop and strike the top surface of the rear bumper. If anyone is sitting or standing on the horizontal surface of the tailgate when both cables fractured, they could fall and be injured. On vehicles without a bumper, the tailgate may drop to a lower position.

**Remedy:** Dealers will replace the galvanized support cables with stainless steel support cables. In addition, dealers are to inspect the tailgate hinge and replace it, if necessary free of charge.


02/18/2007	New Mexico Motor Vehicle Dept. Las Cruces, NM	<b>Registration issued or renewed</b>
------------	---	---------------------------------------

02/18/2008	New Mexico Motor Vehicle Dept. Las Cruces, NM	<b>Registration issued or renewed</b>
------------	---	---------------------------------------

02/21/2010	New Mexico Motor Vehicle Dept. Las Cruces, NM Title #060444S06702861	<b>Registration issued or renewed</b>
------------	---	---------------------------------------

02/20/2011	New Mexico Motor Vehicle Dept. Las Cruces, NM Title #060444S06702861	<b>Registration issued or renewed</b>
------------	---	---------------------------------------


02/17/2013	New Mexico Motor Vehicle Dept. Las Cruces, NM Title #060444S06702861	<b>Registration issued or renewed</b>
------------	---	---------------------------------------


11/07/2013	174,309	West Side Automotive Las Cruces, NM 575-647-8300 teamautomotivellc.com/ ★ 5.0 / 5.0 7 Verified Reviews ♥ 2 Customer Favorites	 <b>Vehicle serviced</b> - Battery/charging system checked
------------	---------	---	--



03/03/2015	New Mexico Motor Vehicle Dept. Las Cruces, NM Title #060444S06702861	<b>Registration issued or renewed</b>
------------	---	---------------------------------------

02/05/2017	New Mexico Motor Vehicle Dept. Las Cruces, NM Title #060444S06702861	<b>Registration issued or renewed</b>
------------	---	---------------------------------------

10/22/2020	New Mexico Motor Vehicle Dept. Las Cruces, NM Title #060444S06702861	<b>Registration issued or renewed</b>
------------	---	---------------------------------------

03/31/2021	194,309	West Side Automotive Las Cruces, NM 575-647-8300 teamautomotivellc.com/ ★ 5.0 / 5.0	 <b>Vehicle serviced</b> - A/C system checked - A/C refrigerant recharged - Cabin air filter replaced/cleaned
------------	---------	---	---

7 Verified Reviews  
 2 Customer Favorites

04/27/2021 194,601 West Side Automotive  
Las Cruces, NM  
575-647-8300  
teamautomotivellc.com/  
 5.0 / 5.0  
7 Verified Reviews  
 2 Customer Favorites





**Vehicle serviced**

- A/C expansion/orifice valve replaced
- A/C refrigerant recharged
- A/C service valves replaced
- A/C system serviced
- Blend/diverter door actuator replaced

10/14/2021 New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM  
Title #060444S06702861

**Registration issued or renewed**

09/27/2022 199,156 West Side Automotive  
Las Cruces, NM  
575-647-8300  
teamautolc.com/  
 5.0 / 5.0  
7 Verified Reviews  
 2 Customer Favorites





**Vehicle serviced**

- Cooling system checked
- Water pump replaced

10/12/2022 New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM  
Title #060444S06702861

**Registration issued or renewed**

10/24/2022 199,282 West Side Automotive  
Las Cruces, NM  
575-647-8300  
teamautolc.com/  
 5.0 / 5.0  
7 Verified Reviews  
 2 Customer Favorites



**Vehicle serviced**

- Automatic transmission pan replaced
- Coil spring(s) replaced
- Fluids checked
- Transmission filter replaced

10/06/2023 New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM  
Title #060444S06702861

**Registration issued or renewed**

09/04/2024 New Mexico  
Motor Vehicle Dept.  
Las Cruces, NM  
Title #060444S06702861

**Registration issued or renewed**

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



**Glossary**

**First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

**Manufacturer Recall**

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)

 [@CARFAXinc](https://twitter.com/CARFAXinc)

 [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2025 CARFAX, Inc., part of S&P Global. All rights reserved.  
10/8/25 12:35:21 PM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 1999 CHEVROLET SILVERADO 1500 vehicle (VIN: 2GCEC19T9X1161719), which is based on information supplied to CARFAX and available as of 10/8/25 at 1:35 PM (EDT).**

\_\_\_\_\_  
Customer Signature

\_\_\_\_\_  
Date

\_\_\_\_\_  
Dealer Signature

\_\_\_\_\_  
Date

The Buyback Guarantee Certificate is not available for this vehicle.